Time-Dependent Response of Soft Soil under Tilted Storage Tanks

Suhit Chakraborty[1] and Amit Kumar Das[2]

[1] M. Tech. Scholar, Department of Civil Engineering, NIT Silchar, Assam - 788 010, India
[2] Assistant Professor, Department of Civil Engineering, NIT Silchar, Assam - 788 010, India
`amitkdas@civil.nits.ac.in`

Abstract. Tilting of foundations due to differential settlement is reported in case of many structures. Such phenomenon may occur due to non-availability of adequate soil data or inappropriate design considerations. In case of a tilted structure founded on soil strata consisting a soft soil layer, it is important to take timely remedial measures. Therefore, it is required to analyze the changes in response of soft soil with time in such cases. In this study, time-dependent behavior of soft foundation soil under tilted cylindrical storage tank is analyzed to develop an overview of the consolidation settlement of soil. The analysis is performed using finite element software package Plaxis 3D. The foundation of the tank is considered as uniformly loaded circular raft made of concrete. A soil layer system is selected for the analysis of differential settlement considering variation in thickness of the soft soil layer along the diameter. Effect of size of raft and stiffness of soft soil is also studied to develop further understanding of the problem. It was observed that differential settlement of tank may occur even in uniform soil layer, but tilting is dependent on change in thickness of the soft soil layer. It was also observed that tilting reduces with increase in stiffness of the soft soil.

Keywords: Tilting, Storage Tank, Soft Soil.

1   Introduction

Cylindrical storage tanks are often considered as one of the most important structures for continuing the proper functioning of the industries. Most of these storage tanks are cylindrical in shape. Storage tanks are often built in coastal regions where in general soft marine clay soils are found. Many times, it was noticed that there was a differential settlement, distortion of the tank and tilting of the structure occurred due to the poor soil condition. So, the design and construction of storage tanks not only limited to superstructure but needs proper soil investigation. Moreover, since such kind of structures is operational for long period so even after construction of such structure, proper monitoring is required.

   Many researchers have studied the behavior of a circular raft foundation considering the steel storage tanks. Brown and Paterson [1] investigated the failure history of oil storage tank founded on sensitive marine clay to determine the suitable bearing

capacity. D'Orazio and Duncan [2] studied the settlement of the steel tank and made an effort to determine the tolerable limit of differential settlement. Also, they defined three different settlement profiles of steel tank. Berardi and Lancellotta [3] conducted a study on oil tank settlement due to the yielding of soil. For this they consider the Critical State concept and plasticity model to incorporate soil behaviour. Zanjani et al. [4] performed numerical analysis and compared the settlement of the steel tanks with available codes by keeping the ratio of tank diameter to height of order four and by varying slenderness ratio. Mistrikova and Jendzelovsky [5] performed the analysis of the circular symmetric tanks resting on elastic subsoil. The authors considered concrete storage tank and simulated foundation soil with different constitutive models to observe the effect on deformation of soil. Ramdane et al. [6] performed the case study of the settlement of oil storage tanks located in the marine terminal of Bejaia. Hotala and Ignatowicz [7] studied the settlement under steel tanks with different foundation arrangements. Deb and Das [8] and Das and Deb [9, 10] also addressed soft soil engineering related to concrete rafts and storage tanks.

Most of this research work was performed considering the steel storage tanks. Also, a study was conducted to check for the differential settlement of steel tanks on the untreated ground. But alongside differential settlement, it is also required to study the tilting phenomenon of the tanks. Moreover, it is also very important to find the reason behind the tilting as well to analyze the changes in the response to soft soil with time. Thus, the present study investigates the time-dependent behavior of soft foundation soil under tilted cylindrical storage tanks considering foundation of the storage tank a circular raft.

2   Modelling

In the present work, a hypothetical soil profile is considered for the numerical analysis to study the tilting and differential settlement of storage tanks. Numerical analysis is performed using finite element software package Plaxis 3D. Details of the soil layers and soil properties of each layer considered for numerical model is shown in Table 1.

Table 1. Soil profile and properties used in the present study

Layers	Soil	Parameters
First	Sand	$c = 0$ kN/m^2, $\phi = 30°$, $E = 30000$ kN/m^2, $\gamma = 16$ kN/m^3, $e = 0.7$, $\mu = 0.3$, $k = 8.64$ m/day, $S = 0$.
Second	Soft Clay	$c_u = 10$ kN/m^2, $\phi = 0°$, $E = 300c_u$ kN/m^2, $\gamma = 17$ kN/m^3, $e = 1.2$, $\mu = 0.4$, $k = 0.000864$ m/day, $S = 1$.
Third	Rock	$c = 20$ kN/m^2, $\phi = 45°$, $E = 150000$ kN/m^2, $\gamma = 21$ kN/m^3, $e = 0.15$, $\mu = 0.15$, Non-Porous.

c = cohesion of soil, ϕ = friction angle, E = modulus of elasticity, μ = Poisson's ratio, e = void ratio, γ = unit weight of soil, k = permeability, S = saturation of soil.

The diameter of the circular raft is assumed as 20 m and it is made of concrete with unit weight, γ = 25 kN/m³ and Young's Modulus, E = 31 x 10⁶ kN/m². The Height of the tank is assumed as 6 m. The overall surcharge acting on the raft due to stored material is considered as 60 kN/m². Ultimate bearing capacity of footing resting on stratified soil layer is determined for the case considering top soil is dense sand and bottom soil layer is saturated soft clay [11]. It is found to be safe. There may be different reasons for tilting of structures of which one of the main reasons is expected to be variable soil layer thickness beneath the structure. In case of large structures like storage tanks, there is a high possibility of change in soil layer thickness beneath the structures. If this soil layer of variable thickness is weak and compressible, then differential settlement and tilting are expected to occur. Four different cases of soil profiles with or without variation in thickness are configured, as shown in Fig. 1, for numerical analysis to evaluate the tilting of the structure.


Fig. 1. Cross-sectional view of four different soil profiles

Initially, convergence study is performed using coarse, medium and fine meshing and medium meshing is found satisfactory enough. The medium meshing technique is adopted for the analysis with 133630 elements and 208254 nodes. 10-noded tetrahedral elements for 3D soil model and 6-noded triangular elements for raft simulated by plate are used in numerical model. Soil layers in the numerical models are simulated using Mohr-Coulomb constitutive model. In all the numerical models side boundaries are partially fixed, while the bottom is fully fixed and the top surface is free. The numerical modelling in Plaxis 3D is performed in five steps: gravity loading, placing of sand layer, construction of tank raft, loading, and consolidation. All the steps, excluding gravity loading, is kept under the consolidation stage considering consolidation of soil a continuous process starting from the construction of tank to loading with surcharge. Among the four configurations mentioned in Fig. 1, configuration 3 is selected for the study of the time-dependent behaviour of the tilted structure. The

model prepared in Plaxis 3D for time-dependent study with configuration 3 is shown in Fig. 2.

Fig. 2. Numerical model developed in Plaxis 3D with Configuration 3 soil profile for time-dependent analysis

3 Validation of Numerical Model

In order to validate the numerical model developed in Plaxis 3D, a case study is selected from Ramdane et al. [6] and the results obtained is compared. Ramdane et al. [6] presented a case of the settlement of hydrocarbon liquids storage tanks located in the marine terminal of Bejaia. After 25 years of construction of tanks, a differential settlement, ovalization and tilting occurred in few tanks. Fig 3 shows the vertical settlements reported by Ramdane et al. [6] and the same obtained from the numerical model developed in Plaxis 3D. The results show good agreement.


Fig. 3. Comparison of vertical settlement between results obtained from present study and Ramdane et al. (2013)

4   Results and Discussion

Fig. 4 shows vertical settlement profile of raft for different soil profile configuration (as shown in Fig. 1) just after the application of surcharge load. Further settlement takes place with the consolidation of soil. The tilting behavior of storage tanks under different configurations is observed, excluding configuration 1, even at this stage, when major consolidation is yet to occur. In case of configuration 1, where each layer has uniform thickness, only differential settlement is observed. This differential settlement is measured as the difference in vertical settlement between the edge and centre of the raft, which is expected if the raft is flexible. At this stage, in configuration 2, 3 and 4, amount of tilting (difference in vertical settlement between two opposite edges) is 20 mm towards right side, 23 mm towards right side and 15 mm towards left side, respectively. It may be noted that the tilting is higher in case of configuration 3 despite the settlement is lower than configuration 2 and 4.


Fig. 4. Vertical settlement profile of raft for different soil profile configuration

Fig. 5 shows vertical settlement for configuration 3 soil profile at different time after application of the surcharge load. The results of the time-dependent analysis show that the raft is tilted by 23 mm up to the loading step of the analysis. The analysis is then continued for further consolidation. Consolidation steps are further sub-divided

into different steps in order to monitor the settlement behaviour of the raft. Finally, settlement up to 90% consolidation data is noted. It is observed that there is an increase in tilting of the tank with further consolidation and after 90% consolidation tilting of the raft is 105 mm. Therefore, ultimate tilting is almost 4.5 times of the initial tilting observed just after application of surcharge.


Fig. 5. Vertical settlement profile of the raft at different time after application of surcharge for Configuration 3 soil profile

Parametric studies are performed to observe the effect of different important factors on tilting of the structure. In parametric studies other parameters are kept unchanged, while tilting is studied for variation of any one parameter. Fig. 6 shows the effect of undrained cohesion (c_u) of soft clay on time-dependent change in tilting of the structure. The change in undrained cohesion, also indicates change in stiffness of soil, since the value of modulus of elasticity (E) for clay soil also changes with undrained cohesion considering $E = 300c_u$. It is observed that with the increase in undrained cohesion of soft soil, as well as an increase in stiffness of the soil, tilting of the structure reduces. It is also observed that the tilting of the structure may become insignificant in stiffer soil.

Fig. 6. Tilting of the raft for different undrained cohesion (c_u) of soft soil


Fig. 7. Time-dependent change in tilting of the structure for different intensity of surcharge

Effect of intensity of surcharge on time-dependent change in tilting of structure is presented in Fig. 7. In this study, undrained cohesion of soft clay (c_u) is considered as 15 kPa to ensure safety against bearing failure. It is observed that the increase in intensity of surcharge causes increase in tilting of structure. Tilting reaches 3 times the initial tilting when intensity of surcharge is 60 kPa, but the same is 3.4 times the initial tilting as observed for 90 kPa surcharge after 500 days. It is also observed that possibility of ultimate tilting is higher when intensity of surcharge is higher. In the present study, tilting is a function of the consolidation settlement, which increases non-linearly with surcharge intensity and time. Therefore, tilting is observed to increase disproportionately with increase in surcharge intensity, because rate of consolidation settlement increases with surcharge intensity, but decreases with time.

Fig. 8 shows the change in tilting with time for different diameter of the raft. It shows that smaller the raft diameter, chances of tilting of structure reduces. Percentage decrease in tilting observed after 500 days is about 37% while diameter of the raft changes from 20m to 15m and the same for change in diameter from 20m to 10m is about 80%. It is also observed that the change in tilting of the structure with time is almost linear for rafts of lower diameter, whereas the same is nonlinear when diameter of the raft is large. Such change in tilting behavior may be attributed to the decrease in relative stiffness of the raft with increase in diameter, while thickness of the raft remains constant.


Fig. 8. Tilting of the raft with change in diameter of the raft

5   Conclusions

Present study shows that the tilting of structure should be studied as a function of time, otherwise the design of appropriate remedial measure may prove to be erroneous or ineffective. Following conclusions are drawn from present study:

(1) Differential settlement may occur even in foundations resting on uniform soft soil, but tilting is governed by change in thickness of compressible soil layer.

(2) Tilting of the structure increases with time as consolidation of the soil progress.

(3) With increase in undrained cohesion of soft clay as well as stiffness of the soil, tilting of the structure reduces.

(4) Larger the diameter of the storage tank, possibility of tilting is higher.

References

1. Brown, J.D., Paterson, W.G.: Failure of an oil storage tank founded on a sensitive marine clay. Canadian Geotechnical Journal 1(4), 205-214 (1964).

2. D'Orazio, T.B. and Duncan, J.M.: "Deferential settlement in steel tank", Journal of Geotechnical Engineering 113(9), 967-983 (1987).

3. Berardi, R., Lancellotta, R.: Yielding from field behavior and its influence on oil tank settlements. Journal of Geotechnical and Geoenvironmental Engineering 128(5), 404-415 (2002).

4. Zanjani, A.A., Fakher, A., Maddah-Sadatieh, S.R.: A numerical study on the effect of uneven settlements of oil storage tank. In: 2nd International Conference on New Developments in Soil Mechanics and Geotechnical Engineering, pp. 238-245. Near East University, Nicosia, North Cyprus (2009).

5. Mistrikova, Z., Jendzelovsky, N.: Static analysis of the cylindrical tank resting on various types of subsoil. Journal of Civil Engineering and Management 18(5), 744–751 (2012).

6. Ramdane, B., Omar, S., Djahid, A.: Differential settlements of cylindrical steel storage tanks: Case of the marine terminal of Bejaia. In: International Conference on Case Histories in Geotechnical Engineering, Paper No. 2.26, Chicago (2013).

7. Hotala, E., Ignatowicz, R.: Effect of settlement of foundations on the failure risk of the bottom of cylindrical steel vertical tanks for liquids. Studia Geotechnica et Mechanica 41(3), 171–176 (2019).

8. Deb, K., Das, A.K.: Distribution of stress on stone column-reinforced soft soil under cylindrical storage tank. Applied Mechanics and Materials 567, 699-704 (2014).

9. Das, A.K., Deb, K.: Modeling of uniformly loaded circular raft resting on stone column-improved ground. Soils and Foundations 54(6), 1212-1224 (2014).

10. Das, A.K., Deb, K.: Response of cylindrical storage tank foundation resting on tensionless stone column-improved soil. International Journal of Geomechanics 17(1), Paper No. 04016035 (2017).

11. Murthy, V.N.S.: Principles and Practices of Soil Mechanics and Foundation Engineering. Marcel Dekker Inc., New York (2002).